Date 16/3/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s [illegible] ADAM GLEN Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp-car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs
		Next Service										Cab Cleaned (Y/N)
Locomotive	2211		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 478076
Fuel added to comp cars/loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1100 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1027		1608	1620	N		1		
2	1655		1750	1823	N		2		
3	1859		1935	2047	N		3	change compressor M to I	
4	2122		2210	2325	N		1		
5	0000		0045	0227	N		2		
6	0307						3	1100L FUEL	
7							1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
2105	Rake 3 compressor M shut down @ Andoom changed to I		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....