Date 03/09/2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM NE Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y / N Rake 2 Y / N Rake 3 Y / N	Rake 1 Rake 2 Rake 3
Loco Comp Oil: OK / Not OK / Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0515	Engine Oil	Comp Car P	Comp Car L		Comp Car O	Comp Car K		Comp Car N	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0623	Comp Oil	Amt Added —	Amt Added —		Amt Added 60 Pumps	Amt Added		Amt Added 12 Pumps	Amt Added		Amt Added
Rake 3	0355	Comp Hrs	17305	11528		33731	8562		36223	18738		Amt Added
		Next Service	18137	12000		34500	9100		36800	19000		Loco Hrs
Locomotive	0546		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Cab Cleaned: COVID
Fuel added to comp cars / Loco			97 Ltr's	Ltr's		Ltr's	Ltr's		271 Ltr's	Ltr's		Loco Km's Travelled 526863
												1600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0412		0452	0458	N		3		
2	0533		0629	0630	N		1		
3	0705	1005	1045	1045	Y		2	Dump Delay LP Down	
4	1120		1210	1226	NO		3		
5	1301		1418	1420	Yes		1	R1 shunt compl cut compJ in	
6	1455		1545	1554	NO		2	fuel loco	
7	1638						3		
8							1		
9							2		
10							3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0550	Comp K rake 2 issues Pumping / stacker Fault		
	Loco Door Latch No2 End broken		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....