Date 31/01/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Glen [✓ Day] Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
[✓ Yes] No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N | Rake 2 Y N | Rake 3 Y N	Rake 1 0 | Rake 2 0 | Rake 3 0

Loco Comp Oil	OK Not OK Topped Up

Record time comp car/loco hrs taken			Rake1 Lead	Rake1 2nd	Rake2 Lead	Rake2 2nd	Rake3 Lead	Rake3 2nd	Locomotive
			Comp Car P	Comp Car T	Comp Car	Comp Car	Comp Car I	Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0435	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0425	Comp Hrs	17540	17217			11731	18997	Loco Hrs 26098
		Next Service	18137	17500			12000	19000	Cab Cleaned COVID
Locomotive	0480		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 529051
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0435	0450	0515	0542			3		
2	0617		0645	0707			1		
3	0742		0815	0837			2		
4	0912		0940	0957			3		
5	1082		1105	1126			1		
6	1155		1222	1241			2		
7	1316		1350	1415			3		
8	1450						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature..