Date 3/10/26 Loco No. RL005 Cab No 2 Facing Andoom Shift Driver/s NV Adam — Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓70	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up										

Record time comp car/loco hrs taken		Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	Comp Hrs							Loco Hrs 26109
	Next Service							Cab Cleaned COVID
Locomotive 1515		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 529324
Fuel added for comp cars / Loco		Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1450.		1537	1539	?		1	fuel loco 2000	
2	1614		1649	1656	N		2		
3	1731		1806	1817	N		3	M/c	NV
4	1852		1929	1939	N		1		NV
5	2014		2046	2104	N		2		NV
6	2139		2218	2226	N		3		
7	2301		2335	2348	N		1		
8	0023		0058	0114	N		2		
9	0149		0225	0235	N		3		
10	0310						1		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature .....