Date 30/7/26 Loco No. 5 Cab No Facing Andoom Shift Driver/s Glen Rob Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car P / Amt Added	Comp Car J / Amt Added	Radiator Water added(mm s/glass) / Amt Added
Rake 2	0920.	Comp Oil	Comp Car / Amt Added	Comp Car K / Amt Added	Comp Car M / Amt Added	Amt Added
Rake 3	0930	Comp Hrs		17090 / 6340	16718 / 18447	Loco Hrs 25463
		Next Service		17057 / 9100	17500 / 19000	Cab Cleaned COVID
Locomotive	0555		Running in Auto / Manual Not Running	~~Running in Auto / Manual~~ Not Running / ~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running / Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 515009
Fuel added to comp cars / Loco			Ltr's	205. Ltr's / Ltr's	188 Ltr's / Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1		0820.	0845	0845.			1		
2	0910		1407	1408			2	Called loco 555 Lights. MC	MC RR
3	1444		1534	1547			5	MC	
4	1623						1		RR.
5									
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 30/7/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Adam / Nev Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 1 Rake 2 1 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken

			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car I	Comp Car N		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service										Loco Hrs
Locomotive	1835		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			20 Ltr's	228 Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled 515184 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1623	1636	1707	1725	N		1		
2	1800		1834	1900	N		2	MCR1	RR AR
3	1935		2012	2036	N		3	MCR2	RR AR
4	2111		2150	2204	N		1		AR
5	2239		2316	2348	N		2		
6	0023		0055	0133	N		3		
7	0209		0240	0325	N		1		
8	0400						2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....