Date 30 / 1 / 26 Loco No. IR1005 Cab No 1 Facing Andoom Shift Driver/s Nev Gary (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓ 50	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 Y N	Rake 1 0 Rake 2 Rake 3
Loco Comp Oil	(Ok) Not OK Topped Up				

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
	Rake 1	0400	Comp Car N	Comp Car J		Comp Car P	Comp Car O		Comp Car	Comp Car		Radiator Water added(mm s/glass)
	Rake 2	0530	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
	Rake 3		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
			Comp Hrs 34987	15496		15430	32753					Loco Hrs 22495
			Next Service 35000	15500		16000	33500					Cab Cleaned COVID
	Locomotive	0445	(Running in Auto / Manual Not Running)	Running in Auto / Manual (Not Running)		(Running in Auto / Manual Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 460462
	Fuel added to comp cars / Loco		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0348	1452	1516	1539	NO		1	ANDOOM one stop	
2	1612						2		
3							3		
4									
5									
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....