Date 30/8/26 Loco No. 21005 Cab No 2 Facing Andoom Shift Driver/s Rob / GLEN Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil (OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3			Comp Hrs							Loco Hrs 25832
			Next Service							Cab Cleaned COVID
Locomotive 1453	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 523615
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1450		1521	1535			2		
2	1611		1643	1700			3		
3	1736		1820	1849			1	Fuel loco 2000L MC R1	RM GM
4	1925		1956	2021			2	MC R2	RK GM
5	2057		2130	2146			3	MC R3	RK GM
6	2222		2255	2313			1		
7	2348		0029	0032			2		
8	0107	0116	0140	0155			3	Refilled loco 1000 Ltrs	
9	0230		0300	0321			1		
10	0356						2		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Rake 1 Stopping short after dumping L.P.		
	2nd Comp Car R3005 and Wagon V2010 failed to Cock		
	Wagons checked and clear		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....