Date 29.4.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Steve Pete Ted Day Night Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (Ok) Not OK Topped up | (Ok) Not Ok Topped Up | Rake 1 Y N Rake 2 Y N Rake 3 Y N | Rake 1 Rake 2 Rake 3 |
| Loco Comp Oil | OK Not OK Topped Up | | | |

| Record time comp car/loco hrs taken | | | Lead Rake1 2nd | | Lead Rake2 2nd | | Lead Rake3 2nd | | Locomotive |
|---|---|---|---|---|---|---|---|---|---|
| Rake 1 | 06:12 | Engine Oil | Comp Car J Amt Added | Comp Car O Amt Added | Comp Car P Amt Added | Comp Car N Amt Added | Comp Car I Amt Added | Comp Car M Amt Added | Radiator Water added(mm s/gless) Amt Added |
| Rake 2 | 0800 | Comp Oil | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added |
| Rake 3 | 1007 | Comp Hrs | 15946 | 32918 | 16153 | 35581 | 10770 | 17898 | Loco Hrs |
| | | Next Service | 16500 | 33500 | 17057 | 26052 | 11000 | 18137 | Cab Cleaned COVID |
| Locomotive | | | Running in Auto / Manual (Not Running) | Running in Auto / Manual (Not Running) | Running in Auto / Manual (Not Running) | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual (Not Running) | Loco Km's Travelled |
| Fuel added to comp cars / Loco | | | Ltr's | Ltr's | Ltr's | Ltr's | Ltr's | Ltr's | Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0445 | | 0518 | 0613 | | | 3 | | SAM |
| 2 | 0648 | | 0725 | 0821 | | | 1 | | SAM |
| 3 | 0856 | | 0928 | 1029 | | | 2 | | SAM |
| 4 | 1104 | | 1140 | 1248 | No | | 3 | | |
| 5 | 1323 | | 1358 | 1503 | No | | 1 | | |
| 6 | 1538 | | | | | | 2 | | |
| 7 | | | | | | | 3 | | |
| 8 | | | | | | | | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | R2 2086 FTL | | |
| | R1 2111 2002 FTL | | |
| | Wipers all good switch in wrong position | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*