Date 25/6/26 Loco No. K1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 Y N Rake 3 (Y) N	Rake 1 6 Rake 2 0 Rake 3 -

Loco Comp Oil ?	(OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car O		Comp Car P	Comp Car L		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1 0356	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0408	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs 16450	38304		16724	8209					Loco Hrs
	Next Service 16500	33500		17057	9100					Cab Cleaned COVID
Locomotive 0618	Running In Auto / Manual (Not Running)	Running In Auto / Manual (Not Running)		Running In Auto / Manual (Not Running)	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 507097
Fuel added to comp cars/Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		5000/1500 Litre

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0405		0455	0459			1	fuel point probs - slow m/c	MH R
2	0533		0608	0625	N		2	m/c	MH R
3	0659		0734	0741	N		3		R + WShop DT
4	0815		0926	0946	N		1	Mayday Andoom/fuel loco	
5	1020		1040	1106	N		2		
6	1140	1150	1225	1228	N		3	Slow dumping	
7	1302	1318	1423	1425	Y		1	(crew break 20 mins) / LP down	
8	0300						2		
9									
10									
11								6300 FUEL	
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0815	fuel point - fixed		
	Did not have time to R3 leakage.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....