Date 29/9/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s TRUDI Craig Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up	Lead	Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd

Record time comp car/loco hrs taken

			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Locomotive
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm s/glass) / Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 26020
		Next Service							Cab Cleaned COVID
Locomotive	2225		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 526951
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1		2144	2214	2229	NO		3		CH
2	2302		2332	2353	NO		1		CH
3	0026		0105	0116	NO		2		CH
4	0150		0223	0252	NO		3		
5	0326							LOCO FUEL 800L	
6									
7									
8									
9								* NO DYNAMIC	
10									
11								BRAKE *	
12								TM CUT OUT - SANDING ISSUE	

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....