Date 3.9.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUX — GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	(Ok) / Not OK / Topped up	(OK) / Not Ok / Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil ?	OK / Not OK / Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd		Lead Rake2 2nd		Lead Rake3 2nd		Locomotive
			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive	1833		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 526647
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2100 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1630		1705	1717	NO		3		RL CM
2	1751		1820	1840	NO		1		RL CM
3	1915		1949	2007	NO		2		RL CM
4	2041		2115	2136	NO		3		
5	2210		2240	2259	NO		1		
6	2333		0008	0022	NO		2		
7	0055	0157		0227	Yes		3	Stacker issues. Fuel loco / Shift change	
8	0300								
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	N° 2 End Drivers side door latch U/S.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 04/09/2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s GLEN ROB (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0730	Engine Oil	Comp Car P	Comp Car J		Comp Car O	Comp Car K		Comp Car N	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0433	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0858	Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service	17361	16970		36747	8566		36226	18751		Loco Hrs 7458
Locomotive	0340		18137	17500		34500	9100		36800	19000		Cab Cleaned COVID
Fuel added to comp cars / Loco			~~Running In Auto / Manual~~ Not Running	Running In Auto / ~~Manual~~ ~~Not Running~~		Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		~~Running In Auto / Manual~~ Not Running	Running In Auto / ~~Manual~~ ~~Not Running~~		Loco Km's Travelled 526871
			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0300		0400	0408			1		
2	0443		0520	0525			2		
3	0600		0635	0647			3		MC RS
4	0722	0805	0830	0830			1		MC RS
5	0905		0935	0950			2	Loco door + Wagon inspections	MC RS
6	1025	1035	1107	1123			3		
7	1159		1328	1329	Y		1	shunt R1	
8	1405		1437	1452			2		
9	1528		1602				3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	shunt R1 2110 & 2093 out 2100 & 2054 in		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....