Date 21/5/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s GARY TRUDT Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	Ok Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1	0635	Engine Oil	Comp Car J / Comp Car O	Comp Car / Comp Car	Comp Car I / Comp Car M	Radiator Water added(mm s/glass)
Rake 2	0330	Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3	0450	Comp Hrs	15976 / 32936	16181 / 32354	10794 / 17903	Amt Added
		Next Service	16500 / 33500	17057 / 36000	11000 / 18137	Loco Hrs
Locomotive	1108		Running in Auto / Manual Not Running / Running in Auto / Manual Not Running	Running in Auto / Manual Not Running / Running in Auto / Manual Not Running	Running in Auto / Manual Not Running / Running in Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	Loco Km's Travelled 497082.7 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0310		0403	0419	NO		2		
2	0452		0527	0606	NO		3		GH 2
3	0639		0710	0747	NO		1		GH 2
4	0820		0856	0933	NO		2		GH 2
5	1006		1045	1118	No		3		
6	1152		1225	1302	No		1		
7	1338		1411	1457	No		2		
8	1538						3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....