Date 02/09/2026 Loco No. L1005 / L1007 Cab No 2 Facing Andoom Shift Driver/s ADAM NEU Day / Night Shift

The following checks are to be performed at shift handover or close as practical

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| Yes / No | Ok / Not OK / Topped up | OK / Not Ok / Topped Up | Rake 1 Y / N, Rake 2 Y / N, Rake 3 Y / N | Rake 1 0, Rake 2 0, Rake 3 6 |
| Loco Comp Oil | 7 Ok / Not OK / Topped Up | | | |

| | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|
| Record time comp car/loco hrs taken | Comp Car P | Comp Car I | | Comp Car O | Comp Car K | | Comp Car N | Comp Car M | | Radiator Water added(mm s/glass) |
| Rake 1 0635 | Amt Added | Amt Added | | Amt Added 50 pump, Might Need | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 2 0450 | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 0826 | Comp Hrs 17290 | 11528 | | 33727 | 8555 | | 36221 | 18738 | | Loco Hrs 25893 |
| | Next Service 18137 | 12000 | | 34500 | 9100 | | 56800 | 19000 | | Cab Cleaned COVID |
| Locomotive 0412 | Running In Auto / ~~Manual~~ / ~~Not Running~~ | ~~Running In Auto / Manual~~ Not Running | | Running In Auto / ~~Manual~~ / ~~Not Running~~ | ~~Running In Auto / Manual~~ Not Running | | Running In Auto / ~~Manual~~ / ~~Not Running~~ | ~~Running In Auto / Manual~~ Not Running | | Loco Km's Travelled 525245 |
| Fuel added to comp cars / Loco | Ltr's | Ltr's | | 185 Ltr's | Ltr's | | Ltr's | Ltr's | | Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0321 | | 0410 | 0416 | NO | | 1 | | |
| 2 | 0451 | | 0531 | 0542 | NO | | 2 | M/c R2 | |
| 3 | 0617 | 0829 | 1110 | 1110 | Yes | | 3 | LP Dumping Issue, Loco Isue R3 R1 | |
| 4 | 1145 | | 1227 | 1300 | N | | 1 | | |
| 5 | 1335 | | 1421 | 1440 | N | | 2 | | |
| 6 | 1515 | | | | | | 3 | | |
| 7 | | | | | | | 1 | | |
| 8 | | | | | | | 2 | | |
| 9 | | | | | | | 3 | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| 0845 | Loco Compressor Problem, Loco Change out | | |
| | Rake 2 comp car O might need compress oil | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*