Date 3/3/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s GARY NEIL Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0735	Engine Oil	Comp Car 5	Comp Car K		Comp Car P	Comp Car N		Comp Car 1	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0350	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0545	Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service	15165	7491		15886	35063		10320	17528		Loco Hrs
Locomotive			16500	8100		16000	36000		11000	18137		Cab Cleaned COVID
Fuel added to comp cars / Loco			Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled
			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2600 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0353		0427	0512	NO		2		
2	0545		0617	0659	NO		3		
3	0732		0805	0912	NO		1		
4	0945		1030	1102			2		
5	1135		1230	1325	NO		3	fuel loco	
6	1400		1443	1525	NO		1		
7	1600								
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....