Date 3/5/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI GARY Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Ø Rake 2 Ø Rake 3 Ø
Loco Comp Oil ?	OK Not OK Topped Up			

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0342	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0506	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0640	Comp Hrs	15990	32936		16198	35600		10794	17936		Loco Hrs
		Next Service	16500	33500		17057	36052		11000	18137		Cab Cleaned COVID
Locomotive	0759		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 497560.8
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0345		0421	0453	No		1		
2	0527		0611	0636	No		2		TR
3	0710		0745	0836	NO		3	Manual load R3	TR
4	0910		0945	1027	NO		1		TR
5	1101		1140	1208	NO		2		
6	1241		1320	1352	NO		3	R2 manual dump	
7	1425		1455	1539	NO				
8	1617								
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Town Whistle not working No 1 end. Country ok		
	R2 manual dump - First 2 wagons - needed wand to dump. One car hang up		
	R2 2086 Washed - FTL		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....