Date 13/7/21 Loco No. R1005 Cab No Facing Andoom Shift Driver/s Ted Steve R Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2	Engine Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
	Comp Hrs									Loco Hrs 25178
Locomotive 1715	Next Service									Cab Cleaned COVID
	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 507958
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1640		1714	1841	No		2		SG
2	1910		1941	2008	No		3		SG
3	2043		2114	2138	No		1		SG
4	2212		2245	2256	N		2		
5	2331		0001	0015	N		3		
6	0050		0119	0135	N		1		
7	0210		0240	0256	N		2		
8	0331						3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature. .....