Date 13/4/26 Loco No. 8005 Cab No Facing Andoom Shift Driver/s Pete (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 6 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up	Lead	Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd

Record time comp car/loco hrs taken			Comp Car J	Comp Car K	Comp Car P	Comp Car N	Comp Car I	Comp Car M	Locomotive
Rake 1	0900	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm e/glass) Amt Added
Rake 2	0620	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0640	Comp Hrs	15860	7082	16100	35375	10623	17787	Loco Hrs 23802
		Next Service	16500	8100	17057	36062	11000	18137	Cab Cleaned COVID
Locomotive	0651		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 482232
**Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0338		0413	0535	N		2	M/C	PH
2	0610		0646	0745	N		3	M/C	PH
3	0820		0856	1005	N		1	M/C	PH
4	1040		1117	1237	N		2		
5	1312		1347	1520	N		3		
6	1550								
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....