Date 13/08/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TROY E GARY Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	OK / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Ø Rake 2 Ø Rake 3 Ø
Loco Comp Oil ?	OK / Not OK / Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car P	Comp Car N		Comp Car O	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0430	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0557	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0627	17139	36114		33498	8454		16836	18550		Loco Hrs
Next Service	18137	36800		34800	9100		17500	19000		Cab Cleaned COVID
Locomotive 0511	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 521861
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0432		0508	0527	NO		1	cc swapped N⇒P	
2	0601		0650	0700	NO		2	" " O→K (Dwell LP track maint)	JR
3	0734		0808	0829	NO		3	M⇒J	JR
4	0903		0938	0959	NO		1		JR
5	1033	1048	1201	1201	Y		2	Crew break, Wshop Ax cc O, fuel	
6	1235		1308	1356	NO		3		
7	1429		1501	1522	NO		1		
8	1555						2		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Wagon#54 Noise reported by track maint R1		
	R2 had to manual dump (cc K) Replaced belt in cc O		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....