Date 13/08/26 Loco No. 1007 Cab No 2 Facing Andoom Shift Driver/s Jed/Steve Day (Night) Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| Yes / No | Ok / Not OK / Topped up | OK / Not Ok / Topped Up | Rake 1 Y N; Rake 2 Y N; Rake 3 Y N | Rake 1; Rake 2; Rake 3 |
| Loco Comp Oil | OK / Not OK / Topped Up | | | |

| | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|
| Record time comp car/loco hrs taken | | | | | | | | | | Radiator Water added(mm s/glass) |
| Rake 1 | Engine Oil | Comp Car | Comp Car | Comp Car | Comp Car | | Comp Car | Comp Car | | Amt Added |
| Rake 2 | Comp Oil | Amt Added | Amt Added | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 | Comp Hrs | | | | | | | | | Loco Hrs |
| | Next Service | | | | | | | | | Cab Cleaned COVID |
| Locomotive | | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | | Loco Km's Travelled |
| Fuel added to comp cars / Loco | | Ltr's | Ltr's | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 1555 | | 1630 | 1650 | | | 2 | | BSH |
| 2 | 1725 | | 1800 | 1818 | | | 3 | | DMH |
| 3 | 1853 | | 1923 | 1947 | | | 1 | | BSH |
| 4 | 2022 | | 2052 | 2120 | | | 2 | | |
| 5 | 2155 | | 2340 | 2340 | Yes | 1h | 3 | Loco 7 Fuel 1500L | |
| 6 | 0015 | | 0100 | 0132 | No | | 1 | Loco 7 shut down Low eng oil swapped for Loco 5 | |
| 7 | 0207 | | 0235 | 0312 | No | | 2 | | |
| 8 | 0347 | | | | | | 3 | Loco 5 Fuel 2300L | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*