Date 14 2 26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Jed Pike Steves Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0400	Engine Oil	Comp Car ~~J~~ J	Comp Car K		Comp Car P	Comp Car O		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0630	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0842	Comp Hrs	35062	7323		15631	32800		10167	17419		Loco Hrs 22855
		Next Service	35000	8100		16000	33500		11000	18137		Cab Cleaned COVID
Locomotive	0442		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ Not Running		Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Loco Km's Travelled 467556
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0400		0441	0552	N		1		
2	0627		0705	0744	N		2	m/c	PH
3	0819		0855	1021	N		3	m/c	PH
4	1056		1219	~~13~~05	No		1	Refuel Loco 1500L	
5	~~13~~40		1415	1514	No		2		
6	1549						3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 14/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Rob Glen Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3										Loco Hrs 22861
										Cab Cleaned COVID
Locomotive 1630	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 467753
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1549		1630	1715			3	MC R3	RR
2	1751		1823	1900			1	MC R1	RR
3	1936		2010	2059			2	MC R2	RR
4	2135		2206	2305			3		
5	2341		0014	0125			1		
6	0200.025.		0240.0353				2	Fuelled Loco 1500 LTRS.	
7	0428						3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....