Date 14 / 05 / 2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM / NEV (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 (C) Rake 2 Rake 3
Loco Comp Oil: (OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car K	Comp Car I		Radiator Water added(mm s/glass)
Rake 1: 0400 — Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2: 0557 — Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3: 0700 — Comp Hrs	16140	32952		16279	35097		8047	10811		Loco Hrs
Next Service	16500	33500		17057	36052		8100	11000		Cab Cleaned COVID
Locomotive: 0653	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Loco Km's Travelled 499050.1
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0423		0500	0601	N		1		
2	0636	1125	1300	1510	Y		2	Tailings flush, Plant Down	
3	1545						3		
4							1		
5							2		
6							3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 14/5/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s TRUDI / GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 4 Rake 2 Rake 3 6
Loco Comp Oil 2	OK Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1200 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1545		1630	1736	NO		3	M/c	
2	1810		1846	1943	NO		1	Swap locos 7 ⇒ 5.	
3	2017		2050	2210	NO		2		
4	2244		2316	0021	NO		3		
5	0054		0125	0231	NO				
6	0304							Fuel loco	
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
1630	AIR CON NOT WORKING NO. 2 END!! LOCO (7)		
1847	R1 swapped CCs as per C2 request		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....