Date 14/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Glen-Rob Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
	OK	OK		0 0 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
OK / Not OK / Topped Up	Comp Car J	Comp Car O		Comp Car P	Comp Car K		Comp Car M	Comp Car I		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 0335	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0500	Comp Hrs 16355	33149		16522	8168		18141	11033		Loco Hrs 24876
Rake 3 0645	Next Service 16500	33500		17057	9100		19000	11000		Cab Cleaned COVID
Locomotive 0350	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~		Loco Km's Travelled 500812
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1501L Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0334		0415	0442			1		MC SM
2	0457		0550	0615			2		MC SM RR
3	0650		0720	0747			3		MC SM RR
4	0822		0850	0920			1		
5	0955		1025	1052			2		
6	1127		1200	1227			3		
7	1303		1344	1402			1	Fuel loco 1501L	
8	1438		1508	1528			2		
9	1604						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Rake 1 Wagon 2110 failed to load		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 14/6/26 Loco No. 5 Cab No 2 Facing Andoom Shift Driver/s Adam / Nev Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	120 ↓ (Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 8 Rake 3 1

Loco Comp Oil: (OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs
	Next Service									Cab Cleaned COVID
Locomotive 1823	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 501 184
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2400 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1604		1658	1658	N		3	STATION PROTECT LOCO ISSUE FOR MCR3	
2	1733		1805	1833	N		1		
3	1908		1945	2006	N		2		
4	2041		2115	2135	N		3		
5	2210		2248	2306	N		1		
6	2341		0015	0041	N		2	R1 NO Telemetry M/c @ Andoom	
7	0130		0203	0238	N		3		
8	0313						1	fuel loco	
9							2		
10							3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....