Date 5/11/26 Loco No. 16003 Cab No 2 Facing Andoom Shift Driver/s PETE STEVE/FARLEY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up	Lead	Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Locomotive
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 26796
		Next Service							Cab Cleaned COVID
Locomotive	2043		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 544203
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	4200 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1547		1620	1635	N		3		
2	1705		1755	1805	N		1	MC	
3	1835		1911	1930	N		2	MC	
4	2005		2042	2053	N		3	MC	
5	2128		2215	2230	N		1		
6	2305		2336	2354	N		2		
7	0029		0107	0117	N		3	LOCO Fuel 2500 + 700	
8	0152		0223	0243	N		1		
9	0318						2	FUEL + 1000	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....