Date 6/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Rob / Glen / Molly Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (OK) Not OK Topped up | (OK) Not Ok Topped Up | Rake 1 Y N Rake 2 Y N Rake 3 Y N | Rake 1 0 Rake 2 0 Rake 3 0 |
| Loco Comp Oil | (OK) Not OK Topped Up | | | |

| | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|
| Record time comp car/loco hrs taken | Comp Car | Comp Car | | Comp Car | Comp Car | | Comp Car | Comp Car | | Radiator Water added(mm s/glass) |
| Rake 1 | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 2 | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 | | | | | | | | | | Loco Hrs 24719 |
| | | | | | | | | | | Cab Cleaned COVID |
| Locomotive 1613 | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Loco Km's Travelled 497307 |
| Fuel added to comp cars / Loco | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | 2300. Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 1604 | | 1638 | 1655 | | | 3 | | |
| 2 | 1731 | | 1802 | 1823 | | | 1 | M/C | RR. |
| 3 | 1859 | | 1930 | 1954 | | | 2 | M/C R1 | RL CM |
| 4 | 2030 | | 2100 | 2130 | | | 3 | M/C R2 | RL OM |
| 5 | 2205 | | 2235 | 2255 | | | 1 | | |
| 6 | 2330 | | 2355 | 0023 | | | 2 | | |
| 7 | 0058 | 0118 | 0143 | 0205 | | | 3 | Refuelled loco 2300 Ltrs Roster change Andoom | |
| 8 | 0330 | | | | | | | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*