Date 22/4/26 Loco No. A1005 Cab No 1 Facing Andoom Shift Driver/s JED [redacted] MOLLY Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up		Rake 1 Y / N Rake 2 Y / N Rake 3 Y / N	Rake 1 Rake 2 Rake 3 0
Loco Comp Oil	OK / Not OK / Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	
Record time comp car/loco hrs taken							Radiator Water added(mm s/glass)
Rake 1	Engine Oil Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	Comp Oil Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	Comp Hrs						Loco Hrs 24030
	Next Service						Cab Cleaned COVID
Locomotive 1819	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 485789
Fuel added to comp cars / Loco	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2270 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1611		1650	~~1645~~ 1705	NO		3		
2	1820		1850	1955	No		1		
3	2030		2105	2215	No		2		MM.
4	2250		2325	0040	No		3		
5	0110		0157	0300	No		1	Refuel Loco	
6	0335						2		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....