Date 11.4.26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Steve Pete (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	Ok (Not OK) Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3

Loco Comp Oil: (OK) Not OK Topped Up

Record time comp car/loco hrs taken

			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car J	Comp Car K		Comp Car D	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	15826	7802		16071	35375		10590	17787		Loco Hrs
		Next Service	16500	8100		17057	36052		11000	18137		Cab Cleaned COVID
Locomotive			Running In Auto / Manual Not Running	Running In Auto / Manual (Not Running)		(Running In Auto / Manual Not Running)	Running In Auto / Manual (Not Running)		(Running In Auto / Manual Not Running)	Running In Auto / Manual (Not Running)		Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0223		0410	0430			2	Andoom Stan.	SM PH
2	0505		0540	0637			3		SM PH
3	0712		0742	0900			1		SM PH
4	0935		1025	1120			2		
5	1155		1246	1342			3		
6	1417		1450	1608			1		
7	1643						2		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	OIL LEVEL 14'16H		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....