Date 11/5/21 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Ted Star Pete (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car	Comp Car		Comp Car P	Comp Car N		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2	0553	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added 24298
		Next Service				16264	35661					Loco Hrs ~~490283~~
Locomotive	0811					17057	36052					Cab Cleaned COVID
			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 490283
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		3100 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0350		0430	0520	NO		1		MC JM
2	0555		0630	0735	No		2		
3	0810		0845	0935	No		3		
4	1010		1045	1205	No		1	REFUEL	
5	1240		1330	1410			2		
6	1445						3	SHUNT COMP CARS.	
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....