Date 11 9 26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Ø Rake 2 Ø Rake 3 Ø

Loco Comp Oil			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
OK Not OK Topped Up			Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken			Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1		Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2		Comp Oil										Loco Hrs
Rake 3		Comp Hrs										Cab Cleaned COVID
		Next Service										Loco Km's Travelled
Locomotive	1750		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		531268
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		3500 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1610		1645	1711	NO		1		
2	1745		1819	1857	NO		2		
3	1931		2000	2024	No		3		
4	2058		2130	2159	NO		1		
5	2232		2309	0002	NO		2		
6	0035		0130	0153	NO		3	Fuel loco	
7	0226		0257	0338	NO				
8	0411								
9								* ENGINE OIL ON ADD *	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....