
[← Back to the previous page](#)

Generations

1.0, 2.0 and 2.0E — incompatible by design, and the engineering reasons why.

The generational split is the technical heart of the system: the two dock families are incompatible, the newer one needs no mains connection, and the intelligence moved from the dock to the bike. There is also a China-market variant that reuses the older dock design — a genuine oddity worth a paragraph when it can be sourced properly. Each generation will get the same treatment the rolling stock pages give a fleet: what it is, what it replaced, and what is still unverified.

An independent, non-commercial reference site. Not affiliated with Taipei Rapid Transit Corporation, Taipei City Government, or any bus operator. Line colours are the official values published by each operator through Taiwan MOTC's open data platform. [About this site.](#)

Station names, codes and sequence from TDX Transport Data eXchange, Ministry of Transportation and Communications, operators TRTC, NTMC, TYMC, and TMRT. Government open data. Retrieved 2026-08-22; source last updated 2016-11-23. The 12 Sanying station records absent from TDX are sourced directly to New Taipei Metro and government publications on their pages. Provenance.