
[← Back to the previous page](#)

Generations

1.0, 2.0 and 2.0E — incompatible by design, and the engineering reasons why.

The generational split is the technical heart of the system: the two dock families are incompatible, the newer one needs no mains connection, and the intelligence moved from the dock to the bike. There is also a China-market variant that reuses the older dock design — a genuine oddity worth a paragraph when it can be sourced properly. Each generation will get the same treatment the rolling stock pages give a fleet: what it is, what it replaced, and what is still unverified.

An independent, non-commercial reference site. Not affiliated with any transit operator or government body in Taiwan. Line colours are the official values published by each operator through Taiwan MOTC's open data platform. [About this site.](#)

Station names, codes and sequence from TDX Transport Data eXchange, Ministry of Transportation and Communications, operators TRTC, NTMC, TYMC, and TMRT. Government open data. Retrieved 2026-08-24; source last updated 2016-11-23. The 12 Sanying station records absent from TDX are sourced directly to New Taipei Metro and government publications on their pages. Provenance.