


KISELRING


kinetic wall piece · nine silicon mirrors · one slow revolution




9 × Ø300 mm silicon · 9 printed towers · 1 motor · 0 visible hardware
assembly ≈ 45 min · two people for the hang · USB-C power



READ ME, THEN BREATHE



mirrors: EDGES ONLY · never flex



tape bonds ONCE — the wafer lands and stays

IPA ✓

acetone ✗

clean prints with alcohol — acetone eats PLA

glue tonight


spin tomorrow

pinion epoxy/CA takes the stall torque — full cure first




two people for the hang. one for everything else.

IN THE BOX




tower segment

×9




Ø300 silicon mirror

×9




12T pinion

×1




motor dock

×1



motor band

×1




saddle

×1

also: N20 motor (6 V · 15 rpm) ×1 · M5 flathead ×4 · M5 square nut ×4
acrylic foam tape · CA glue · USB-C cable · drywall anchors or a stud

1

×9




no sliding after touchdown

ONE LANDING


lower by the edges, centred over the pad — gravity does the rest



2




lap tab into pocket — slide until flush




nine laps close the circle — mirrors face the room

3



≈ 700 mm




4 × M5 into square nuts · anchors, or a stud (better)

THE WALL CARRIES EVERYTHING

two mounts on the 25 mm grid — nothing else ever touches the wall



4




lower the ring into the saddle — it rests, nothing clamps

TWO PEOPLE. MIRROR EDGES ONLY.



5




teeth touch — no squeeze

slide the dock until the pinion just meshes the rim,
then tighten. it should spin by finger, silently.

the joint sees full stall torque at takeoff — cure before power

6



PLUG IN. WALK AWAY.

USB power · one revolution every four minutes · forever

