**Batch Record Report** 5957004 - Obesity SDD 0.25mg/0.5 ml D

## Regular production



**BRR** status Released MO status Finished Valid from

MBR for MO version 00000001

MBR ID/Version/Description 5957004/0000032/Obesity SDD 0.25mg/0.5mlD

30000 ea Order size Batch no. NHJM068881 MO no. NHJM00013246

BRR Approval		
Status	Text	MBR fulfilled
Batch Record Report NHJM	100013246	
Released	Automatically released by system	
		Date - User: 2023-09-14 10:35:22 +0100 - 111111111 /
MBR fulfilled: yes		

Review	w status		
Revie	w step	Status	Number of elements
Except	ion review	Executed	0
	Batch record report review (Exception)		
			Date - User: 2023-09-14 10:22:47 +0100 - 270 / Nishranth Mahesh (nhjm)
CPP re	eview	Not needed	0
CQA re	eview	Not needed	0

Basic operations			
Basic operation	SFO ID	оророр	opopop
0100 - SDD assembly	806363	2023-09-14 08:18:28 +0100	2023-09-14 10:20:34 +0100

Summing bill of input material				
Material no.	Material name	Target quantity	opopop	No. of positions
2700145	FRONT ASSEMBLY_MK2, NN WHITE	20000 ea	20000 ea	1
2701018	REAR ASSEMBLY, NN WHITE,	0.5 20000 ea	20000 ea	1
5185500	SEMAGLUTIDE D 0.5MG/ML,PF 0.5	S 20000 ea	20000 ea	1

Produced batches						
Material no.	Material name	Batch no.	Expiration date	оророр	оророр	opopop
						quantity
5957004	Obesity SDD 0.25	NHJM068881	2029-09-14 23:59 +0100	2023-09-14 10:06:30 +0100	2023-09-14 10:35:20	19703 ea
	mg/0.5 ml D				+0100	

Basic operation: 0100 - SDD assembly

Batch no.: NHJM068881

Pos.	Material n	о.	Material na	ame	Manufacturing	g date set Target quar	ntity 이	оорор
0001	5185500		SEMAGLU <sup>*</sup> 0.5	TIDE D 0.5MG/ML,PF	S No	20000 ea	20	000 ea
	Action	SU		Batch no.	Scale ID	Scale quantity	Takeout quantity	Effective quantity
	Take over	123400004868	171362	NHJM068882	 Date - User: 202	 3-09-14 09:57:47 +0100 -	10000 ea - 121 / PAS-X	10000 ea Production Operat
	Take over	123400004868	171386	NHJM068882	 Date - User: 202	 3-09-14 09:58:12 +0100	10000 ea - 121 / PAS-X	10000 ea Production Operat
Pos.	Material n	0.	Material na	ame	Manufacturing	g date set Target quar	ntity 0	оорор
0002	2700145		FRONT AS WHITE	SEMBLY_MK2, NN	No	20000 ea	20	000 ea
	Action	SU		Batch no.	Scale ID	Scale quantity	Takeout quantity	Effective quantity
	Take over	123400004868	171461	NHJM068884	 Date - User: 20	 023-09-14 09:57:03 +010	10000 ea 00 - 270 / Nish	10000 ea Iranth Mahesh (nhir
	Take over	123400004868	171423	NHJM068884		 023-09-14 09:57:15 +010	10000 ea	10000 ea
Pos.	Material n	0.	Material na	ame	Manufacturing	g date set Target quar	ntity O	оорор
0003	2701018		REAR ASS	EMBLY, NN WHITE, (	).5 No	20000 ea	20	000 ea
	Action	SU		Batch no.	Scale ID	Scale quantity	Takeout quantity	Effective quantity
	Take over	123400004868	171485	NHJM068885	 Date - User: 202	 3-09-14 09:56:22 +0100 ·	10000 ea - 121 / PAS-X	10000 ea Production Operat
	Take over	123400004868	474500	NHJM068885			10000 ea	10000 ea

Bill of	target material / Sto	ock creation log				
Pos.	Material no.	Material name	Batch no.	Material flow type	Target quantity	оророр
0001	5957004	Obesity SDD 0.25mg/0.5 ml D	NHJM068881	Stock	30000 ea	19703 ea
	SU		Action			оророр
	35710869160005	55130	Stock creation			10000 ea
				Date - User: 2023-09-14 10:06:	30 +0100 - 270 / Nis	hranth Mahesh (nhjm)
	35710869160005	55147	Stock creation			9703 ea
				Date - User: 2023-09-14 10:07:	18 +0100 - 270 / Nis	hranth Mahesh (nhjm)

Materia	l reconciliation - Inp	out material					
Pos.	Material				Accounted		Status
0001	5185500 - SEMAC	GLUTIDE D 0.5MG/I	ML,PFS 0.5		99,425 % ()		· ·
	Batch	Take-out	Return	Loss	Produced	Difference	
	Total	20000 ea	0 ea	0 ea	19885 ea	115 ea	
	NHJM068882	20000 ea	0 ea	0 ea			

Material reconciliation - Target material			
Material	Target	оророр	Samples
5957004 - Obesity SDD 0.25mg/0.5 ml D	30000 ea	19703 ea	182 ea

Date - User
Buto Coor
2023-09-14 10:20:23 +0100 - 112 / PAS-X Production Support
2023-09-14 10:19:17 +0100 - 112 / PAS-X Production Support

Production unit	
Basic operation	Production unit
0100 - SDD assembly	DF0601AL

Basic operation: 0100 - SDD assembly

Batch no.: NHJM068881

Check lists		
Check list: ID kvittering	Number of sample	es using this list: 1
	OK	Ikke OK
	1	
Check list: IPC kvittering	Number of sample	es using this list: 1
	ОК	Ikke OK
	1	
Check list: OPC kvittering	Number of sample	es using this list: 2
	OK	Ikke OK
	2	
Check list: Reference kvittering	Number of sample	es using this list: 2
	OK	Ikke OK
	2	

Samples	3						
ID	Sample type	Variant	Check list	Product counter	SU	Sample quantity	Critical results
REF1	REF	AUTOMATIC	Reference kvittering	10		35 ea	OK
		Date:	2023-09-14 08:47:54 +01	100		User: 121/PAS-X Pro	oduction Operator
		PCS [	Date: 2017-06-15 11:33:3	2,861			Verification:
OPC1	OPC	AUTOMATIC	OPC kvittering	30		40 ea	OK
		Date:	2023-09-14 08:48:25 +01	100		User: 121/PAS-X Pro	oduction Operator
		PCS [	Date: 2017-06-15 11:33:3	2,861			Verification:
ID1	PFS-ID	AUTOMATIC	ID kvittering	30		10 ea	OK
		Date:	2023-09-14 08:49:00 +01	100		User: 121/PAS-X Pro	oduction Operator
		PCS [	Date: 2017-06-15 11:33:3	2,861			Verification:
IPC1	IPC	AUTOMATIC	IPC kvittering	30		20 ea	OK
		Date:	2023-09-14 08:49:35 +01	100		User: 121/PAS-X Pro	oduction Operator
		PCS [	Date: 2017-06-15 11:33:3	2,861			Verification:
OPC2	OPC	AUTOMATIC	OPC kvittering	30		12 ea	OK
		Date:	2023-09-14 09:19:58 +01	100		User: 121/PAS-X Pro	oduction Operator
		PCS [	Date: 2017-06-15 11:33:3	2,861			Verification:
REF2	REF	AUTOMATIC	Reference kvittering	10		65 ea	OK
		Date:	2023-09-14 09:23:41 +01	100		User: 121/PAS-X Pr	oduction Operator
		PCS [	Date: 2017-06-15 11:33:3	2,861			Verification:

Bill of	of equipment				
Pos.	Equipment class	Equipment type	Equipment	Number of items	
1	Workroom	ASSEM / Assembly Line	AL0601 / Assembly Line 06.01	1	

D	etaile	ed BO						
L	evel	Step				Status		
1		1 - 0100STR - Ops	tartsaktiviteter	Subtype:	Tabular execution: no	NF		
	Funktion håndterer alle opstartsaktiviteter: - Back-to-Back vurdering - Back-to-Back bekræftelse - Batchinformation (PID Board Information) - Allokering af udstyr - Prøveudtagnings beregninger - Batch download og start							
L	evel	Step				Status		
4	2	1 - N0100DEC - Ba	ack to back?	Subtype:		NF		
		Back to Back vælges vælges ja. Hvis ikke,	•	tes umiddelbart efter for	gående batch. Opfylder denne ordre kriterierne for en back-to-b	ack-ordre,		
П		Decision type: User s	selection	Predecessor: Start	Repetition: 1			
П		Set value	opopop		User & date / Signature	Status		
П			N0100Yes			NF		
Ц				User & date	e: 2023-09-14 08:22:24 +0100 - 270 / Nishranth Mahesh (nhjm)	, in the second second		

Basic operation: 0100 - SDD assembly
Batch no.: NHJM068881

Level Step Status Subtype: ---Tabular execution: no 1 - N0110B2B - Bekræft back to back NF Denne funktion bekræfter valget af Back-to-Back 2.0 010 - Bekræft back to back Subtype: --оророр User & date / Signature Set value Status Bekræft at back to back Bekræft at back to back betingelserne er opfyldt NF betingelserne er opfyldt User & date: 2023-09-14 08:33:28 +0100 - 270 / Nishranth Mahesh (nhjm) Block signature: 2023-09-14 08:33:42 +0100 - 121 / PAS-X Production Operator Verification signature: 2023-09-14 08:33:56 +0100 - 114 / PAS-X Production Operator 2 Level Step Status 1 - N0140AL - [A] Alloker linje Tabular execution: no NF Subtype: ---Funktionen allokerer linje til ordren. Hvis" ERROR" er linjen allokeret til en anden ordre. Status □ 3 1 - M0130AL - [A] Linje allokering Subtype: ---NF Allokerer linje til aktuelle ordre. Linjen kan ikke allokeres, hvis status ikke er OK. opopop User & date / Signature Status Set value ASSEM: Assembly Line / NF ASSEM:Assembly Line / Workroom:AL0601 (Assembly Line 06.01) Workroom:AL0601 (Assembly User & date: 2023-09-14 08:33:57 +0100 - 111111111 / ---Line 06.01) **Attributes** Identification type: Scan Reuse equipment: no Equipment item: 1: Workroom AL0601 Assembly Line 06.01 Level Step Status 1 - N0230CAL - [A] Subtype: ---Tabular execution: no NF Prøveudtagsberegninger Beregner prøve udtag ud fra valgte ordre. 2.0 010 - Batch Size in Pens Subtype: --оророр User & date / Signature Set value Status 30000 ea User & date: 2023-09-14 08:33:58 +0100 - 111111111 / -2.1 020 - IPC Subtype: ---1. Udtags mængde оророр Set value User & date / Signature **Status** 20 ea User & date: 2023-09-14 08:33:59 +0100 - 111111111 / ---2.2 030 - OPC Subtype: ---1. Udtags mængde Set value opopop User & date / Signature **Status** 52 ea NF User & date: 2023-09-14 08:33:59 +0100 - 111111111 / 040 - Reference Subtype: ---1. Udtags mængde оророр Set value User & date / Signature Status 100 ea User & date: 2023-09-14 08:33:59 +0100 - 111111111 / --2.4 050 - ID Subtype: ---1. Udtags mængde opopop Set value User & date / Signature Status 2 ea NF User & date: 2023-09-14 08:33:59 +0100 - 111111111 / ---Level Step Status 1 - N0250MBA - [A] Batch start Subtype: ---Tabular execution: no NF Udfører batchstart mellem PAS-X og linjen.

Regular MO no.: NHJM00013246

Basic operation: 0100 - SDD assembly Batch no.: NHJM068881

teria					Ctatu
	Step				Statu
<u> 3</u>	1 - M0150DEC - [A] Start M	IOT udført?	Subtype:		NF
	Decision type: Formula		Predecessor: M0140MOT	Repetition: 1	
	Set value	opopop		User & date / Signature	Statu
		M0150Yes			NF
				User & date: 2023-09-14 08:37:05 +0100 - 111111111 /	
vel	Step				Statu
3	1 - M0160DEC - [A] Start F	A udført ?	Subtype:		NF
	Decision type: Formula		Predecessor: M0161FA	Repetition: 1	
	Set value	оророр		User & date / Signature	Statu
	Oet value			Oser & date / Oignature	
	<b> </b>	M0160Yes			NF
<u> </u>				User & date: 2023-09-14 08:36:53 +0100 - 111111111 /	
val	Step				Statu
		FOdf40	Outhfrance		
3	1 - M0170DEC - [A] Start P	rs udiørt?	Subtype:	5 44	NF
	Decision type: Formula		Predecessor: M0171PFS	Repetition: 1	
	Set value	оророр		User & date / Signature	Statı
		M0170Yes			NF
				User & date: 2023-09-14 08:37:14 +0100 - 111111111 /	
	Step				Stati
3	1 - M0180DEC - [A] Start R	A udført?	Subtype:		NF
	Decision type: Formula		Predecessor: M0181RA	Repetition: 1	
	Set value	оророр		User & date / Signature	State
		M0180Yes			NF
		10100103		User & date: 2023-09-14 08:37:24 +0100 - 111111111 /	141
<u> </u>				Oser & date: 2023-09-14 00:37:24 10100 - 111111111	
vel	Step				Stati
vel	Step	load	Subtyne:	Tabular execution: no	
evel	1 - 0110MAN - [A] Redown	load	Subtype:	Tabular execution: no	
evel		load	Subtype:	Tabular execution: no	
	1 - 0110MAN - [A] Redownl Trin til redownload	load	Subtype:	Tabular execution: no	NF
evel	1 - 0110MAN - [A] Redownl Trin til redownload		·	Tabular execution: no	NF Statu
vel	1 - 0110MAN - [A] Redownl Trin til redownload Step 1 - N0100DEC - [A] Redow	nload	Subtype:		NF Statu
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redowl Denne funktion er 'Nej' som st	nload	Subtype: til 'Ja' ved behov for redowi	nload.	NF Statu
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som step of the ste	<b>nload</b> andard. Ændres	Subtype:	nload. Repetition: 1	Statu NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som standard becision type: Formula  Set value	nload andard. Ændres opopop	Subtype: til 'Ja' ved behov for redowi	nload.	State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som step of the ste	<b>nload</b> andard. Ændres	Subtype: til 'Ja' ved behov for redowi	nload. Repetition: 1	State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som standard becision type: Formula  Set value	nload andard. Ændres opopop	Subtype: til 'Ja' ved behov for redowi	nload. Repetition: 1	State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som st. Decision type: Formula  Set value	nload andard. Ændres opopop	Subtype: til 'Ja' ved behov for redowi	nload. Repetition: 1 <b>User &amp; date / Signature</b>	State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redow Denne funktion er 'Nej' som st Decision type: Formula  Set value Step	nload andard. Ændres opopop N0100No	Subtype: til 'Ja' ved behov for redowi	Nload.  Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /	State NF State State State
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som stander Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale	nload andard. Ændres opopop N0100No	Subtype: til 'Ja' ved behov for redowi	nload. Repetition: 1 <b>User &amp; date / Signature</b>	State NF State State
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redow Denne funktion er 'Nej' som st Decision type: Formula  Set value Step	nload andard. Ændres opopop N0100No	Subtype: til 'Ja' ved behov for redowi Predecessor: Start	Nload.  Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /	Statu NF Statu
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug	nload andard. Ændres opopop N0100No	Subtype: til 'Ja' ved behov for redowi Predecessor: Start	Nload.  Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /	Statu NF Statu NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownl Denne funktion er 'Nej' som st Decision type: Formula Set value Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step	nload andard. Ændres opopop N0100No e registering på linjen.	Subtype: til 'Ja' ved behov for redowi Predecessor: Start	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownload  Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug	nload andard. Ændres opopop N0100No e registering på linjen.	Subtype: til 'Ja' ved behov for redowi Predecessor: Start	Nload.  Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownl Denne funktion er 'Nej' som st Decision type: Formula Set value Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step	nload andard. Ændres opopop N0100No e registering på linjen.	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype:	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownl Denne funktion er 'Nej' som st Decision type: Formula  Set value Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom.	nload andard. Ændres opopop N0100No e registering på linjen.	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype:	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redow Denne funktion er 'Nej' som st Decision type: Formula  Set value Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty	nload andard. Ændres opopop N0100No e registering på linjen.	Subtype:  til 'Ja' ved behov for redown Predecessor: Start  Subtype: Subtype:	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redow Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom.  010 - Udfør Line Empty 1. Før batchstop -Stop udstyre	nload andard. Ændres opopop N0100No e registering på linjen. nje er tom	Subtype:  til 'Ja' ved behov for redown Predecessor: Start  Subtype: Subtype:	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no	State NF State NF State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownl Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom.  010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop	Subtype:  til 'Ja' ved behov for redown Predecessor: Start  Subtype: Subtype:	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redow Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom.  010 - Udfør Line Empty 1. Før batchstop -Stop udstyre	nload andard. Ændres opopop N0100No e registering på linjen. nje er tom	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: vitter eventuelle watchdogs	User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no  Og kritiske alarmer. Bekræft at linjen er tom.  User & date / Signature	Statu NF Statu NF Statu NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownl Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom.  010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: vitter eventuelle watchdogs	Repetition: 1  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no	State NF State NF State State NF
vel	1 - 0110MAN - [A] Redownl Trin til redownload  Step 1 - N0100DEC - [A] Redownl Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom.  010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value  OK	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: vitter eventuelle watchdogs	User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no  Og kritiske alarmer. Bekræft at linjen er tom.  User & date / Signature	Statu NF Statu NF Statu NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value OK  Step	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: Vitter eventuelle watchdogs User & date: 20	Tabular execution: no  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature	Statu NF Statu NF Statu NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value OK  Step 1 - N0180MBI - Batch stop	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop  OK	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: vitter eventuelle watchdogs	User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no  Og kritiske alarmer. Bekræft at linjen er tom.  User & date / Signature	State NF State NF State NF State State NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value OK  Step	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop  OK	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: Vitter eventuelle watchdogs User & date: 20	Tabular execution: no  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature	State NF State NF State NF State State NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value OK  Step 1 - N0180MBI - Batch stop Trin i forbindelse med afslutnir	nload andard. Ændres  opopop  N0100No  registering på linjen.  nje er tom  et -Tøm linjen -Kv opopop  OK	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: Vitter eventuelle watchdogs User & date: 20	Tabular execution: no  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature	Statu NF Statu NF Statu NF
vel	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value  OK  Step 1 - N0180MBI - Batch stop Trin i forbindelse med afslutnir	nload andard. Ændres  opopop N0100No  registering på linjen.  yje er tom  et -Tøm linjen -Kv opopop OK	Subtype:  til 'Ja' ved behov for redowi Predecessor: Start  Subtype:  Subtype:  Subtype:  itter eventuelle watchdogs  User & date: 20  Subtype:	Tabular execution: no  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no  User & date / Signature  23-09-14 10:08:32 +0100 - 270 / Nishranth Mahesh (nhjm)  Tabular execution: no	Statu NF Statu NF Statu NF
vel 1.0	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value OK  Step 1 - N0180MBI - Batch stop Trin i forbindelse med afslutnir	nload andard. Ændres  opopop N0100No  registering på linjen.  yje er tom  et -Tøm linjen -Kv opopop OK	Subtype: til 'Ja' ved behov for redowi Predecessor: Start  Subtype: Subtype: Subtype: Vitter eventuelle watchdogs User & date: 20	Tabular execution: no  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature  Tabular execution: no  User & date / Signature	Statu NF Statu NF Statu NF
evel 1.0	1 - 0110MAN - [A] Redown Trin til redownload  Step  1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step  1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step  2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value  OK  Step  1 - N0180MBI - Batch stop Trin i forbindelse med afslutnir  Step  1 - LNCLR - Linje Clearance	nload andard. Ændres  opopop N0100No  registering på linjen.  yje er tom  et -Tøm linjen -Kv opopop OK	Subtype:  til 'Ja' ved behov for redowi Predecessor: Start  Subtype:  Subtype:  Subtype:  itter eventuelle watchdogs  User & date: 20  Subtype:	Tabular execution: no  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no  User & date / Signature  23-09-14 10:08:32 +0100 - 270 / Nishranth Mahesh (nhjm)  Tabular execution: no	Statu NF Statu NF Statu NF Statu NF
vel 1.0	1 - 0110MAN - [A] Redown Trin til redownload  Step 1 - N0100DEC - [A] Redown Denne funktion er 'Nej' som st Decision type: Formula  Set value  Step 1 - 0150MAT - [A] Materiale Scan komponenter ind til brug  Step 2 - N0170LEM - Bekræft lin Bekræft linjen er tom. 010 - Udfør Line Empty 1. Før batchstop -Stop udstyre Set value  OK  Step 1 - N0180MBI - Batch stop Trin i forbindelse med afslutnir	nload andard. Ændres  opopop N0100No  registering på linjen.  et -Tøm linjen -Kv opopop OK	Subtype:  til 'Ja' ved behov for redowi Predecessor: Start  Subtype:  Subtype:  Subtype:  itter eventuelle watchdogs  User & date: 20  Subtype:	Tabular execution: no  User & date / Signature  User & date: 2023-09-14 08:37:26 +0100 - 111111111 /  Tabular execution: no  Tabular execution: no  User & date / Signature  23-09-14 10:08:32 +0100 - 270 / Nishranth Mahesh (nhjm)  Tabular execution: no	Statu NF Statu NF Statu NF

Basic operation: 0100 - SDD assembly Batch no.: NHJM068881

Material: 5957004 - Obesity SDD 0.25mg/0.5 ml D Level Step **Status** 4 1 - NO161ALC - Zone 1 Subtype: ---Tabular execution: no NF 4.0 10 - LC1 Subtype: ---1. Udfør line clearance og kvitter opopop User & date / Signature Set value Status Ok Ok NF User & date: 2023-09-14 10:11:07 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:11:21 +0100 - 121 / PAS-X Production Operator Level Step Status 4 1 - NO162ALC - Zone 1 NF Subtype: ---Tabular execution: no 4.0 10 - LC2 Subtype: ------1. Udfør line clearance og kvitter opopop Set value User & date / Signature Status Ok Ok User & date: 2023-09-14 10:11:27 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:11:36 +0100 - 114 / PAS-X Production Operator 2 Level Step Status 4 3 1 - CBF3 - Line Clearance Zone 2 NF Subtype: ---Tabular execution: no Level Step Status 4 1 - NO161ALC - Zone 2 Subtype: ---Tabular execution: no NF 4.0 10 - LC1 Subtype: ---1. Udfør line clearance og kvitter оророр Set value User & date / Signature Status Ok Ok User & date: 2023-09-14 10:11:44 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:11:54 +0100 - 121 / PAS-X Production Operator Level Step Status 4 1 - NO162ALC - Zone 2 Subtype: ---Tabular execution: no NF 4.0 10 - LC2 Subtype: ---1. Udfør line clearance og kvitter opopop Set value User & date / Signature **Status** Ok Ok NF User & date: 2023-09-14 10:12:00 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:12:09 +0100 - 114 / PAS-X Production Operator 2 Level Step Status | ↓ 3 | 1 - CBF2 - Line Clearance Zone 3 Subtype: ---Tabular execution: no NF Level Step Status 4 1 - NO161ALC - Zone 3 Subtype: ---Tabular execution: no NF 4.0 10 - LC1 Subtype: ---1. Udfør line clearance og kvitter оророр Set value User & date / Signature **Status** Ok Ωk User & date: 2023-09-14 10:12:18 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:12:27 +0100 - 121 / PAS-X Production Operator Level Step Status 4 1 - NO162ALC - Zone 3 Subtype: ---Tabular execution: no NF 4.0 10 - LC2 Subtype: ---1. Udfør line clearance og kvitter Set value opopop User & date / Signature **Status** Ok Ok NF User & date: 2023-09-14 10:12:32 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:12:42 +0100 - 114 / PAS-X Production Operator 2 Level Step Status → 3 1 - CBF4 - Line Clearance Zone 4 Subtype: ---Tabular execution: no NF

Basic operation: 0100 - SDD assembly Batch no.: NHJM068881

Material: 5957004 - Obesity SDD 0.25mg/0.5 ml D Level Step **Status** 4 1 - NO161ALC - Zone 4 Tabular execution: no Subtype: ---NF 4.0 10 - LC1 Subtype: ---1. Udfør line clearance og kvitter opopop User & date / Signature Set value Status Ωk Ok NF User & date: 2023-09-14 10:12:50 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:12:59 +0100 - 121 / PAS-X Production Operator Level Step Status 4 1 - NO162ALC - Zone 4 Tabular execution: no NF Subtype: ---4.0 10 - LC2 Subtype: ---1. Udfør line clearance og kvitter opopop Set value User & date / Signature Status Ok Ok User & date: 2023-09-14 10:13:05 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:13:21 +0100 - 114 / PAS-X Production Operator 2 Level Step Status 4 3 1 - CBF1 - Line Clearance Zone 5 Tabular execution: no NF Subtype: ---Level Step Status 4 1 - NO161ALC - Zone 5 Subtype: ---Tabular execution: no NF 4.0 10 - LC1 Subtype: ---1. Udfør line clearance og kvitter оророр Set value User & date / Signature Status Ok Ok User & date: 2023-09-14 10:13:31 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:13:40 +0100 - 121 / PAS-X Production Operator Level Step Status 4 1 - NO162ALC - Zone 5 Subtype: ---Tabular execution: no NF 4.0 10 - LC2 Subtype: ---1. Udfør line clearance og kvitter opopop Set value User & date / Signature **Status** Ok Ok User & date: 2023-09-14 10:13:46 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 10:13:57 +0100 - 114 / PAS-X Production Operator 2 Status Level Step 1 - 0140MANU - Manuel prøver Subtype: ---Tabular execution: no NF Registrering af manuelle prøver Level Step Status 1 - N0100DEC - Manuel prøver Subtype: ---NF Predecessor: Start Decision type: Formula Repetition: 1 Set value opopop User & date / Signature **Status** N0100No User & date: 2023-09-14 08:37:26 +0100 - 111111111 / --Status Level Step 1 - N0210ERL - Kassation Subtype: ---Tabular execution: no NF Kasser materiale og kvittér Level Step **Status** 1 - N0220ERL - Kassation 1, kontrol Tabular execution: no Subtype: ---NF 2.0 010 - Kassation 1. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter opopop User & date / Signature Set value **Status** 10 NF User & date: 2023-09-14 09:36:16 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:36:28 +0100 - 121 / PAS-X Production Operator

Regular MO no.: NHJM00013246

Basic operation: 0100 - SDD assembly Batch no.: NHJM068881

Level Step **Status** Tabular execution: no 1 - N0230ERL - Kassation 2. kontrol Subtype: ---NF 2.0 010 - Kassation 2. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter opopop User & date / Signature Set value Status 10 NF User & date: 2023-09-14 09:36:43 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:37:36 +0100 - 114 / PAS-X Production Operator 2 Level Step Status 2 - N0220ERL - Kassation 1. kontrol Subtype: ---Tabular execution: no NF 2.0 010 - Kassation 1. kontrol Subtype: ------1. Kasser PFS/Pen og kvitter opopop Set value User & date / Signature Status User & date: 2023-09-14 09:42:45 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:42:55 +0100 - 121 / PAS-X Production Operator Level Step Status 2 - N0230ERL - Kassation 2. kontrol Subtype: ---Tabular execution: no NF 2.0 010 - Kassation 2. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter Set value оророр User & date / Signature **Status** 5 NF User & date: 2023-09-14 09:43:00 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:43:10 +0100 - 121 / PAS-X Production Operator Level Step Status 3 - N0220ERL - Kassation 1. kontrol Tabular execution: no NF Subtype: ---2.0 010 - Kassation 1. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter Set value opopop User & date / Signature Status 5 User & date: 2023-09-14 09:43:40 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:43:57 +0100 - 121 / PAS-X Production Operator Level Step Status 3 - N0230ERL - Kassation 2. kontrol Tabular execution: no Subtype: ---2.0 010 - Kassation 2. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter Set value оророр User & date / Signature **Status** NF User & date: 2023-09-14 09:44:03 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:44:14 +0100 - 114 / PAS-X Production Operator 2 Level Step Status 4 - N0220ERL - Kassation 1. kontrol Subtype: ---Tabular execution: no NF 2.0 010 - Kassation 1. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter Set value opopop User & date / Signature Status User & date: 2023-09-14 09:44:27 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:44:35 +0100 - 114 / PAS-X Production Operator 2 Level Step Status 4 - N0230ERL - Kassation 2. kontrol Subtype: ---Tabular execution: no NF 2.0 010 - Kassation 2. kontrol Subtype: ---1. Kasser PFS/Pen og kvitter оророр Set value User & date / Signature Status 5 User & date: 2023-09-14 09:44:40 +0100 - 270 / Nishranth Mahesh (nhjm) User identification signature: 2023-09-14 09:44:50 +0100 - 121 / PAS-X Production Operator

Basic operation: 0100 - SDD assembly Batch no.: NHJM068881

Level Step Status 1 - N0200FC - Optælling Subtype: -Tabular execution: no NF Kontrol af antal prøver sammenhold med prøverudtagnings plan Level Step **Status** 1 - N230CAL - [A] Forbrug Subtype: ---Tabular execution: no NF Kontrol af antal prøver sammenhold med prøverudtagnings plan 2.0 010 - OPC Subtype: --оророр User & date / Signature **Status** Set value >=52 ea 52 ea User & date: 2023-09-14 10:16:02 +0100 - 111111111 / --2.1 020 - IPC Subtype: --opopop Set value User & date / Signature **Status** 20 ea >=20 ea User & date: 2023-09-14 10:16:02 +0100 - 111111111 / --2.2 030 - REF Subtype: --оророр Set value User & date / Signature Status 100 ea >=100 ea NF User & date: 2023-09-14 10:16:02 +0100 - 111111111 / --2.3 040 - ID Subtype: -opopop Set value User & date / Signature **Status** >=2 ea 10 ea NF User & date: 2023-09-14 10:16:03 +0100 - 111111111 / ---050 - PFS/Pen manuel kassation Subtype: --оророр User & date / Signature Status Set value User & date: 2023-09-14 10:16:03 +0100 - 111111111 / -060 - PFS automatiske kasserede Subtype: --opopop Set value User & date / Signature **Status** 100 User & date: 2023-09-14 10:16:03 +0100 - 111111111 / ---2.6 070 - PFS, indskannede Subtype: --оророр User & date / Signature Set value Status -- ea 20000 ea NF User & date: 2023-09-14 10:16:04 +0100 - 111111111 / ---2.9 100 - Stock Creation Subtype: -opopop User & date / Signature Status Set value 19703 User & date: 2023-09-14 10:16:04 +0100 - 111111111 / ---110 - Udbytte 2.1 Subtype: ---0 opopop User & date / Signature Status Set value 80 - 120 % 99,425 % User & date: 2023-09-14 10:16:05 +0100 - 111111111 / --2.1 Subtype: ---120 - Tilladt afvigelse opopop User & date / Signature Set value **Status** 200 User & date: 2023-09-14 10:16:05 +0100 - 111111111 / ---2.1 130 - Afvigelse Subtype: --opopop Set value User & date / Signature Status 200 - 200 0 NF User & date: 2023-09-14 10:16:05 +0100 - 111111111 / -Level Step **Status** 1 - N240REP - Gentag recon beregning Subtype: ---NF Decision type: User selection Predecessor: N230CAL Repetition: 1 оророр User & date / Signature **Status** Set value N240Yes User & date: 2023-09-14 10:17:23 +0100 - 270 / Nishranth Mahesh (nhim)

Material: 5957004 - Obesity SDD 0.25mg/0.5 ml D

MO no.: NHJM00013246 Regular

Level Step Status 2 - N230CAL - [A] Forbrug Subtype: --Tabular execution: no NF Kontrol af antal prøver sammenhold med prøverudtagnings plan 2.0 010 - OPC Subtype: --оророр User & date / Signature Set value Status >=52 ea 52 ea NF User & date: 2023-09-14 10:17:54 +0100 - 111111111 / ---020 - IPC Subtype: --оророр User & date / Signature Set value Status =20 ea 20 ea User & date: 2023-09-14 10:17:55 +0100 - 111111111 / --030 - REF Subtype: --оророр Set value User & date / Signature **Status** >=100 ea 100 ea NF User & date: 2023-09-14 10:17:55 +0100 - 111111111 / -2.3 040 - ID Subtype: -оророр User & date / Signature Set value **Status** 10 ea >=2 ea NF User & date: 2023-09-14 10:17:55 +0100 - 111111111 / ---2.4 050 - PFS/Pen manuel kassation Subtype: --opopop Set value User & date / Signature **Status** User & date: 2023-09-14 10:17:55 +0100 - 111111111 / --2.5 060 - PFS automatiske kasserede Subtype: --opopop Set value User & date / Signature Status 100 NF User & date: 2023-09-14 10:17:56 +0100 - 111111111 / --2.6 070 - PFS, indskannede Subtype: --оророр Set value User & date / Signature **Status** 20000 ea NF User & date: 2023-09-14 10:17:56 +0100 - 111111111 / ---2.9 100 - Stock Creation Subtype: -оророр Set value User & date / Signature **Status** 19703 User & date: 2023-09-14 10:17:57 +0100 - 111111111 / ---2.1 110 - Udbytte Subtype: ---0 opopop User & date / Signature **Status** Set value 80 - 120 % 99,425 % NF User & date: 2023-09-14 10:17:57 +0100 - 111111111 / --120 - Tilladt afvigelse Subtype: --оророр Set value User & date / Signature **Status** 200 User & date: 2023-09-14 10:17:57 +0100 - 111111111 / --130 - Afvigelse Subtype: --opopop User & date / Signature **Status** Set value 200 - 200 0 NF User & date: 2023-09-14 10:17:57 +0100 - 111111111 / Level Step Status 2 - N240REP - Gentag recon beregning Subtype: ---NF Predecessor: N230CAL Decision type: User selection Repetition: 2 оророр Set value User & date / Signature **Status** N240No NF User & date: 2023-09-14 10:18:10 +0100 - 270 / Nishranth Mahesh (nhjm)

Basic operation: 0100 - SDD assembly

Batch no.: NHJM068881

AS-X-triggered exceptions aused at	Type	Criticality	Deviation number
23-09-14 09:51:46 +0100	оророр	Noncritical	
lated object: SDD assembly(1 popop ception text (user): test	1)->[A] Materiale registering(1)->[	A] Manuel take out(1)	
Status	Priority	Criticality	Deviation number
Generated	1 / Major	Noncritical	
Correct decision	i / ineje.		51:56 +0100 - 270 / Nishranth Mahesh (nl
		Signature: 2023-09-14 09:	51:51 +0100 - 270 / Nishranth Mahesh (nl
Cluster Operation	1 / Major		
<b>Comment:</b> Exception added t test	to cluster C00001345.		
Exception added to cluster			21:38 +0100 - 270 / Nishranth Mahesh (n
		Signature: 2023-09-14 10:	21:38 +0100 - 270 / Nishranth Mahesh (n
Acknowledged Comment: test	1 / Major	Noncritical	
Acknowledge an exception		User & date: 2023-09-14 10:	22:20 +0100 - 270 / Nishranth Mahesh (n
Acknowledge an exception		Signature: 2023-09-14 10:22:1	6 +0100 - 113 / PAS-X Production Operat
23-09-14 10:05:59 +0100	оророр	Noncritical	
	1)->[A] Materiale registering(1)->[		
ception text (user): test			
Status	Priority	Criticality	Deviation number
Generated	1 / Major	Noncritical User & date: 2023-09-14 10:	 06:18 +0100 - 270 / Nishranth Mahesh (n
Correct decision		Signaturo: 2022 00 14 10:06	:15 +0100 - 121 / PAS-X Production Oper
Cluster Operation	1 / Major		.13 TO TOO - 12171 AS-X T TOUGCHOIT OPER
Comment: Exception added to test	•		<del></del>
Exception added to cluster		User & date: 2023-09-14 10:	21:38 +0100 - 270 / Nishranth Mahesh (n
		Signature: 2023-09-14 10:	21:38 +0100 - 270 / Nishranth Mahesh (n
Acknowledged	1 / Major	Noncritical	
Comment: test  Acknowledge an exception		User & date: 2023-09-14 10:	22:20 +0100 - 270 / Nishranth Mahesh (n
Acknowledge an exception		Signature: 2023-09-14 10:22:1	6 +0100 - 113 / PAS-X Production Opera
00.00.44.40.00.04.40400	Laborate also de la constante		
23-09-14 10:20:34 +0100 elated object: 806363 (NHJM0	,	Noncritical	from DCC. Check for final planes accords
ecuted.	RDERCONTROLUUUZ . IIICUIIIPI	ete system comiguration ioi imai alaim	from PCS. Check for final alarm cannot be
Status	Priority	Criticality	Deviation number
Generated	1 / Major	Noncritical	
Comment: test	•	User & date: 2023-09-14 10:	20:34 +0100 - 270 / Nishranth Mahesh (ni
NNEndShopFloorOrderWithW	arning		20:33 +0100 - 270 / Nishranth Mahesh (ni
Cluster Operation	1 / Major		
Comment: Exception added t	•		
test  Exception added to cluster		User & date: 2023-09-14 10:	21:38 +0100 - 270 / Nishranth Mahesh (ni
		Signature: 2023-09-14 10:	21:38 +0100 - 270 / Nishranth Mahesh (n
Acknowledged Comment: test	1 / Major	Noncritical	

Acknowledge an exception

User & date: 2023-09-14 10:22:20 +0100 - 270 / Nishranth Mahesh (nhjm)

Signature: 2023-09-14 10:22:16 +0100 - 113 / PAS-X Production Operator 3