DSP LAB Midterm Q1 Part B

Jingyuan Li (jl10915)

One artifact when sliding the frequency slider is that the changing frequency causes a blur to the audio. Because when processing each block, the frequency is updated at the same time, but the last output frame is calculated using older frequency. To fix this artifact, we can stop the processing when the frequency slider is pressed, and when the slider is released, we reset the output list to all zeros to start a new process.