

CS-001 Part, Mold & Material Labeling

Doc ID	CS-001
Title	Part, Mold & Material Labeling
Revision	A
Status	Draft — pending Lead signature (OUTLINED — complete before first use)
Effective date	2026-07-12
Supersedes	Unlabeled everything

Approvals

Role	Name	Date
Author	Simon Starbuck (drafted w/ Claude — SN6 Resources)	2026-07-12
Reviewer	simon (reviewer agent)	
Approver (Composites Lead)		

Revision history

Rev	Date	Author	Description of change
A	2026-07-12	Claude	Initial outline

1. Purpose

Unlabeled molds sat blocking shared storage for weeks while nobody was sure whose they were (PP-10), and unlabeled offcuts made “wait, which gsm is this?” a weekly guessing game (PP-09). So: everything physical gets a label that points back to a record.

2. Scope

Molds, parts (from demold onward), tooling-board stock, cloth rolls/offcuts, mixed-chemical containers, and storage boxes.

3. References

Ref	Document	Where
R1	PP-09, PP-10	FEB-COMP-PP-001
R2	CS-013 (the WO the label points to), CS-011 (home locations)	this series

4. Definitions

- **Label** — durable marker (paint pen / sharpie on tape / tag) carrying at minimum: **ID, owner, home location**.

5. Equipment & Materials

Paint pens, masking tape, zip tags. Nothing that needs ordering approval.

6. Safety

No hazards. Never label directly on a mold's working surface.

7. Procedure (outline — expand on first revision)

1. **Molds:** label on a flange/back face at glue-up (CS-003 §7.3): `WO-ID · part name · ME · home location`. Update location line when it moves (matches `WO mold.location`).
2. **Parts:** on demold, tape label inside/on a trim area: `WO-ID · part name`. After trim, move label to a hidden face or keep with the part's bag.
3. **Cloth:** every roll and every usable offcut bag gets `gsm + weave + source` (e.g. “195 twill Sigmatex”). Unlabeled cloth may not be used on parts (only practice).
4. **Mixed chemicals:** cup/pot labels: `contents + mix time + who`. Anything unlabeled and curing gets treated as hot waste (CS-008).
5. **Boxes/storage:** box label = `contents class + home shelf` (CS-011 storage map ID).

8. Quality checks / acceptance criteria

Check	Target	Method	Record where
Every mold in shared space labeled	100%	Monthly stock walk (CS-011)	Walk notes
No unlabeled cloth in the cutting area	100%	Spot check	—

9. Records

None beyond the labels themselves and WO location fields.