

PACIFIC HVAC SERVICES

Synthetic maintenance vendor

INVOICE

SYNTHETIC TEST INVOICE - NOT VALID - DO NOT PAY

FROM	BILL TO	SERVICE PROPERTY
Pacific HVAC Services 100 Test Fixture Avenue San Francisco, CA 94103 vendor-pacific-hvac	Northstar Properties Accounts Payable 200 Demo Ledger Street San Francisco, CA 94103	Harbor Center 300 Synthetic Plaza San Francisco, CA 94105 property-harbor-center

INVOICE NUMBER	INVOICE DATE	DUE DATE	WORK ORDER
PH-1048	July 8, 2026	July 22, 2026	WO-4821

Invoice line items

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
Rooftop compressor replacement - RTU-4	1	\$9,200.00	\$9,200.00
Emergency installation labor	8	\$325.00	\$2,600.00

Subtotal	\$11,800.00
Tax (8.25%)	\$973.50
TOTAL	\$12,773.50

Payment information

TEST PAYMENT DETAILS ONLY. No bank account, routing number, tax identifier, or real payment instruction is present in this document. Submit through the InvoiceOps synthetic workflow only.

Service detail and extraction ground truth

This second page intentionally exercises multi-page asynchronous expense analysis. All names, identifiers, addresses, and amounts are synthetic.

SERVICE FIELD	SYNTHETIC VALUE
Service date	July 7, 2026
Equipment	Rooftop unit RTU-4
Technician	Taylor Demo
Service location	Harbor Center - roof mechanical area
Work order	WO-4821
Authorization	Synthetic approval reference AUTH-TEST-221

Expected Textract expense fields

FIELD	EXPECTED VALUE
VENDOR_NAME	Pacific HVAC Services
INVOICE_RECEIPT_ID	PH-1048
INVOICE_RECEIPT_DATE	07/08/2026
DUE_DATE	07/22/2026
SUBTOTAL	11800.00
TAX	973.50
TOTAL	12773.50
PO_NUMBER	WO-4821

SYNTHETIC TEST INVOICE - NOT VALID - NEVER SUBMIT FOR PAYMENT