



Quality Defect Report (v 2)

Completed by: **Timothy Chaffee**

Job: -

Completed at: **Sep 2, 2026 9:21 am**

Location: **42.6082113, -83.9428589**

Date issue discovered*

Sep 2, 2026

Job*

Howell south west

Elevation / Door Opening*

24A e12

Replacement needed?*

- Yes
- No

Problem type*

- Extrusion Defect
- Fitment Issue
- Hardware Prep Issue
- Missing Hardware
- Missing Vinyl
- Missing Accessories (Setting blocks, screws, ect)
- Missing Stops
- Length/Size Issue
- Other

Short Description of Issue*

Labeled cut size 119½ actually 119⅞

Picture of issue *

NO ANSWER?

