


- Copy to Desktop
- Run as Admin






- Type 1 and click
 Enter
- The Rockwell Services are disabled
- Reboot
- Login again
- Run Tool again







Type 2 and click
 Enter






 Follow simple instruction







- Login to windows
- Use Rockwells Application
 Manager to restore backup





- Enable Rocwell Services
 Use if you just want to
 re enable the services
- Help for more info and guide

