308DU0

Welcome to Junsi iCharger 308DUO

Bug Fixes ======
035: Correct the "2120" error triggered accidentally.
Note ====
//////////////////////////////////////
Part support
======================================
New Features =======
Bug Fixes
032: Change the default value of discharge voltage for Nixx battery from 0.1V to 0.8V. 033: Solve the invalid problem of " detect if the main port and the balance port charging matching" in the V2.14. 034: Solve the balance regenerative discharge never completes problem.
Note ====
//////////////////////////////////////
Part support
308DUO
New Features =======
* Increase the number of display for program running.  * Add the feature to detect if the main port and the balance port charging matching.
Bug Fixes
25: Revise the PID control parameter, and weaken the fluctuation problem of low charge current.  026: Improve the problem of endless low charge current  027: Correct "Balance Over Charge" does not start problem.  028: When user sets the "user " from "Servo Test", the parameter is failed to check reasonably.  029: Correct the problem that fails to restart the offline resistance measurement after charging.  030: Correct the instantaneous current display problem when starts charging.  031: Solve the problem that fails to display sometimes when connecting big internal resistance load voltage battery.
Note ====
//////////////////////////////////////

Part support

## New Features

========

\* Added a protected program in "regenerative to input mode", if the input power is the power supply, the charger will detected automatically, and shut down automatically, to avoid damaging the power supply.

## Bug Fixes ======= 023: Fix the charge and discharge cycle problem. 024: Fix the startup problem of charging and discharging synchronization of V2.12. Note ==== Version: V2.12 // IIDate of Release: 2014/02/20 // // CWF // Owner: // Part support ========= 308DU0 New Features \_\_\_\_\_ \* Modify the current setting step. st Ignore the knob rolling signal before time within 50ms, and after time within 500ms by pressing the knob. avoid some wrong operation. Bug Fixes ======= 015: Fix some display problems. 016: Improve small current fluctuation problem of discharge. 017: Correct "1401" error caused by battery trickle occasionally. 018: modify the "Banlance Over Charge" setting to 50mV max. 019: Improve shutdown control program. 020: Modify the discharge capacity limit default from 120% to 90%. 021: Correct "1401" error bug caused by regenerative discharge occasionally. 022: Correct the conflict of loading configuration files on SD card. Note ==== // Version: V2.11 // // Date of Release: 2013/12/26 // // Owner: **CWF** // Part support ========= 308DU0 New Features ========= \* Add the "Knob sensitivity" setup. Bug Fixes =======

010: Correct the display bug of cycle option on German version.

011: Correct the device reboots problem when transfers the Log files.

012: Correct the problem of the missing character "\_" when inputs file name.

013: Correct the bug of time display.

014: Modify the version display format "x.x.x" to "x.xx".

```
Note
====
//
          Version:
                        V2.10
                                             //
//
           Date of Release: 2013/11/13
                                             //
//
           Owner:
                        CWF
                                             //
Part support
=========
308DU0
New Features
=========
st Add the "Charging battery" into the entry of "Channel Join" of Channel Regenerative Discharge.
* Add the capacity indicator of the input power supply.
* Add the capacity limit of the Regenerative to input.
* Add the Cycle Mode option: "CHG->DCHG CHG" "DCHG->CHG DCHG" "CHG->DCHG STO" "DCHG->CHG STO".
Bug Fixes
=======
007: Correct the bug of Cycle charge when the Channel Regenerative Discharge starts.
008: Improve the anti-sparking program.
009: Solve the white screen problem when powering on sometimes.
Note
====
//
           Version:
                        V2.09
                                             //
//
           Date of Release: 2013/09/30
                                             //
//
           Owner:
                        CWF
Part support
=========
308DU0
New Features
=========
Bug Fixes
=======
006: Correct the bug for 2006 error triggered accidently.
Note
====
//
           Version:
                        V2.08
                                             //
//
           Date of Release: 2013/09/27
                                             //
//
           Owner:
                        CWF
                                             //
Part support
=========
308DU0
New Features
=========
Bug Fixes
005: Correct the Cycle defect problem of NiZn battery.
```

Note

==== V2.07 // Version: // Date of Release: 2013/09/25 // // // Owner: CWF // Part support ========= 308DU0 New Features ========= Bug Fixes ======= 003: Solve the problem of V2.06: when running storage on the CH1, the CH2 cannot work normally. 004: Change some German text. Note ==== V2.06 Version: // Date of Release: 2013/09/12 // // CWF // Owner: // Part support ========= 308DU0 **New Features** ========= Bug Fixes ======= 001: Solve the charger frozen problem with V2.05.

002: Solve the problem of current increasing slowly on the regenerative mode to channel.

Note ====

Version: V2.05 // // Date of Release: 2013/08/27 // Owner: CWF // 

Part support ======== 308DU0

New Features ========

Bug Fixes =======

Note ====