<<NETWORK CONFIGURATION>>

<Interface> <Node Type> <Node Firmware Ver.> <MAC Address> <Node name>

<Active services>

WirelessLAN on Firmware Ver.H (Sep 16 2015 19:33:48)

BRWC038969ACAAE

BRNC038969ACAAE

BINARY_P1 TEXT_P1 POSTSCRIPT_P1 PCL_P1

BRNC038969ACAAE_AT

<Protocols> TCP/IP Enabled NetBIOS/IP Enabled Enabled Enabled LegacyAuth LPD IPP Enabled Enabled Network scan TFTP Enabled LLMNR Enabled Brother Online Con. Disabled

IPv6 APIPA SNMP Raw Port WebServices FTP mDNS Proxy

Disabled Enabled Enabled Enabled Enabled Enabled Enabled Disabled

2410539

23270

89

777987

<IP Settings>
IP Address Subnet Mask IP Gateway Boot Method Boot Tries IP Filter

192.168.19.112 255.255.255.0 192.168.19.1 DHCP (via DHCP)

GW Timeout (sec) DNS Address Config Primary DNS Server Secondary DNS Server 21 AUTO 192.168.19.1 0.0.0.0

<NetBIOS Name> <WINS Address Config>
<Primary WINS Server> <Secondary WINS Server> BRWC038969ACAAE AUTO

0.0.0.0 0.0.0.0

Disabled

<mDNS Service Name>

Brother DCP-J152W

<WebServices Name>

Brother DCP-J152W [c038969acaae]

<Comm. Mode> <Name(SSID)> <Authentication Mode> <Encryption Mode> <Wireless Link Status>
<Tx Power Code>

Infrastructure Damianowo WPA/WPA2-PSK

AES

Link OK, 11n(13Mbps), Receiving Signal=2, Operating Ch=1 Full, 226, 0, 0

<Network Statistics> Packets Received Bytes Received Packets Transmitted Bytes Transmitted

2423896 930759537 799050 113897658

<Wireless Statistics> RX Frames Received OK RX Frames Error TX Frames Transmitted OK TX Frames Error