

Switch Control Truth Table								
	S1=F S2=F S3=F	S1=T S2=F S3=F	S1=T S2=T S3=F	S1=F S2=T S3=F	S1=F S2=T S3=T	S1=F S2=F S3=T	S1=T S2=F S3=T	S1=T S2=T S3=T
SW=O PM=P PS=P	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing
SW=O PM=N PS=P	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing
SW=O PM=N PS=N	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing	Do Nothing (2)	Do Nothing (2)
SW=O PM=P PS=N	Do Nothing	Do Nothing	PS->P	PS->P	PS->P (2)	Do Nothing	Do Nothing (2)	PS->P
SW=C PM=P PS=P	Do Nothing	PS->N	PS->N (1,2)	Do Nothing	Do Nothing (2)	PM->N	PS->N (2)	PS=PM (1,2)
SW=C PM=N PS=P	Do Nothing	Do Nothing	Do Nothing (1,2)	SW->O	Do Nothing (2)	Do Nothing	Do Nothing	Do Nothing (1,2)
SW=C PM=N PS=N	Do Nothing	Do Nothing	Do Nothing (1,2)	SW->O	SW->O	Do Nothing	Do Nothing (1,2)	Do Nothing (1,2)
SW=C PM=P PS=N	Do Nothing	Do Nothing	Do Nothing (1,2)	PS->P	SW->O	PM->N	Do Nothing	Do Nothing (1,2)
Note 1: Train appears to be strattling the switch								
Note 2: Possible rolling stock on side or main track								