Stockwith. M. J. & Or

50 Lincoln.

21 ft + m s l

YEAR	1850	1851	1832	1853	1854	1855	1856	1857	1858	1859	MEANS.
January							1.94	2.47	.37	.60	
February							1.02	.50	.27	1-01	
March							.22	1.33	1.15	1.00	
April							2.15	2.97	1.64	2.90	
May						.91	2.36	. 87	1.54	.56	
June						1.98	1.21	3.53	1.51	2.09	
July						4.77	1.25	1.32	2.21	.47	
August						.85	4.69	8-50	3.14	3.26	
September -		2.0				.32	2.75	2.27	1.96	3.16	
October		1 849							3.56		
November -		Bank!				1.01	.91	.01	1.05	1.02	
December -		OF SE	E AND			.50	1.65-	.14	1.59	1.55	
Totals -		16					1-41	26.22	19.99	19.85	1

+ Ground 3this 21ft+m sl

~		1
Jro	nt-	6.

	rem - c.											
L	YEAR	1860	1861	1062	1863	1864	1865	1866	1867	1840	1869	MEANS.
	January									158		
	February											1.148
H	March									1.00		
1	April									1.36		
	May											
	June									. 45		
	July											
	August											2.526
H	September -									2.76		
	October	1.35										
1	November -											
1	December -	1.40	1.01	1.06	1.13	1.53	.51	1.44	1.53	5:33	2.81	1-775
	Totals -	26.46	18.25	19.71	20.00	17:13	21.06	2441	22:57	21.48	22.40	21.347
		4	1,0	-	6	-(C	C	C		0	

Average 12 gr 21.43

RAINFALL AT Gainstrowagh Stockwith

Diameter	9										
Height											
Altitude	21										
YEAR	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	МЕ
January	66	.73	2.23	1.96	-69	2.20	1.39	2 33	134	.65	1.4
February											
March											
April											
May											
June											
July											
August											
September											
October											
November	1.39	1.22	2.91	1.39	2.02	3.68	2.89	1.14	2.12	1.71	2.0
December	2.34	1.14	2.84	.16	1.22	.86	4:90	1.45	1.52	.81	1.7

RAINFALL AT Stockwith 80

Lut				Lon			nunty of_	Lu	neor	In	
		Rain G	lauge, by_						42		· 60.
Trent 6											
Diameter	9										
Height	3.6										
Altitude											
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS
January	./2	54	2.53	2.62	2.81	1.32	3.21	1.84	.48	1.64	1.71
February										1.42	1
March					1:55						
April					1:11						1-65
May		1.34	2.63	1.66	. 62	2.05	5.06	1.55	-69	4.47	
June	3.38	1.75	3.64	2.68	748	3:52	.78	-23	2.12	. 40	1.89
July					2.98					1.71	
August					1.81						2.24
					.99						2.31
October											
November,	2.40	2.20	3.48	2.89	1:14	2.45	1.28	1.79	3.69	.27	2.15
December	2.43	2.45	4.23	1.22	1.81	1.03	3.98	.86	1.99	-98	2.09
TOTALS	31.00	2407	3.130	2016	17:10	21:54	26.87	15.57	23.39	26.95	25.54

RAINFALL AT E Stockwith

Lat.				Lon.		Con	enty of	20	col		
Frest - 6		Rain (Tauge, by			Observ	DEO*	m f	°+L	R C.	
Diameter	9										
Height	3.6										
Altitude	21										
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	2.17	1-10	1.05	1.24	1.19	3.17	-68	1.70	.47	1.76	1-453
February				2-14							
March											1.085
April											1.252
May											1.679
June											2.096
July											2-472
August	2-21	2.83	2.05	1.39	1.77	1.92	1.46	2.93	3.10	1.10	2096
September											1.444
October											2-459
November											1.852
December											1.822
"Totals	19.92	25.08	20:30	20.69	20-61	23.90	19.80	20.50	17.98	20.15	20.893

RAINFALL AT Greatferstal Rail Co Rain Gauge, by Lbank - 5. Diameter . . 9 Height ... Altitude 21 1906 1907 1908 1909 MEANS. Year ... 1900 1901 1902 1903 1904 1905 January 2.50 .91 .76 1.53 .61 2.38 .54 1.41 .87 .82 1233 February 1.33 1.20 .73 2.44 .58 2.31 1.20 1.75 .51 March 50 1.46 1.29 2.18 1.86 1.271.08 2.75 2.69 April98 .47 1.69 2.04 1.43 2.13 1.12 1.85 May 1.15 .66 2.50 2.07 .47 1.94 2.89 . 89 June 1.43 1.50 2.13 1.45 1.54 2.45 1.51 July 1.80 2.62 1.85 3.41 2.30 .35 August 3.60 4.23 1-72 2-61 3.01 2-66 1.26 1.74 2.06 September. 1.00 3.80 1.46 1.19 .77 .65 October. 2.61 1.54 2.17 6.12 5.09 3.95 . 41 1.26 November

1-21 .76 2.28

.75 1.41

2.02

December .

2.45 1.36

2.81 4.24 1.60

TOTALS . . 24.29 20.63 20.22 28.26

2.22 1.82

.47

18.27 15.50

1.76 2.49 1.26

21.36 22.21 19.25 24.47

.96 .30 1.538

thus

3.82 2.061

21446

RAINFALL at Stockwith

County of Northinghamehori Observer freak Central Railway (5)

River Barin Instit. Lep Barth Filhertonis 5

Rain Gauge, by___

Diameter	9										
Height	3.6										
Altitude	21										
Year	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January	1.52	.99	3.01	3 - //	1.17	2.03	.38	2.57	1.24	2.97	
February	1.56	.75	1.08	.76	.80	2.11	2.91	.72	1.33	2.19	
March										3.03	
April										1.73	
May	2.39	.87	2.23	1.56	1.66	1.28	2.48	1.42	2.05	- 72	
June	2.52	3.17	5.25	.71	1.47	.68	2.03	1.43	.78	1.15	
July	2.76	. 25	3.54	. 31	2.25	5.08	1.45	.75	2.82	2.62	
August	2.94	2.42	4.33	1.05	2.11	4.14	3.19	4.74	1.89	1-93	
September	.17	2.25	1.35	2.57	.65	1.00	1.39	.66	4.14	1.61	
October										2.34	
November	2.77	2.17	2.43	1.75	1.87	1.89	2.53	1.13	1.81	1.91	
December	3.06	3.93	2.42	1.19	4.09	4.81	2.03	.68	3.44	3.16	
Totals	24.34	20.74	30.94	19.53	20.76	25.59	24.54	19-60	22.45	25.36	

Marie A processor and the second								
Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.

Jan Fe Ma

RAINFALL at Stockwith

County	of no	otting	hams	hire.		Observer	Greo	t Ges	stral	Rail	way Go.	
			- Left									
		Rain	Gauge, b	y								
				10								Total Section
meter	9											
ght	3.6											Distance of the last
itude	21											
Tear	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	MEANS.	
uary	2.19	1.68	2.62									
oruary												i
reh	2.11	.80	1.51									
ril												
у	2.26	1.80	1.03									į

Position of	Station on Map, 2 mile	reduced O. to 1 inch	rdnance Survey } N	Vo. of Map	Reference No),
Date.	Lat. N.	Long.	Railway Station.	Distance Direction from gauge	Parish Church.	Distance Directio