

3 ways to use our ECAD Schematic Symbols & PCB footprints



Automatically load models into your library and attach them to your cursor by clicking our icon on any website.

WATCH VIDEO



Excel plug in. Search for parts from within Excel, customise the fracturing and export to your chosen ECAD Tool.


WATCH VIDEO



You may download our symbols & footprints in the format of your ECAD system for manually loading into your library.

MORE INFO

LIBRARY LOADER.





DOWNLOAD: http://componentsearchengine.com/LibraryLoader.php



ECAD PART WIZARD.

Offers engineers full control of the symbol fracturing and symbol pin positions (left, right, top, bottom). ECAD Symbols & footprints can be downloaded directly from within the EPW application or from manufacturer and RS Component website.



DOWNLOAD: http://componentsearchengine.com/EPW.html



DIRECT MODEL DOWNLOAD FOR MANUAL USE.

Our Schematic Symbols and PCB Footprint can be downloaded in a zip file for the user to manually load into their existing ECAD Library.



DOWNLOAD: http://componentsearchengine.com

