



Fig. 3
The six jumpers are indicated on the parts placement guide by line segments.
Note that C9, C10, C11 and C12 do not mount on the circuit board, but behind the front panel.