



Sodium hydroxide · 2.5kg / 5kg / 25kg pearl

Caustic Soda

Drain unblocker & heavy-duty degreaser

Corrosive**Add to water****Not for**

severe skin & eye burns never water to caustic aluminium, zinc, galvanised

Caustic Soda is sodium hydroxide (NaOH) in pearl form — a powerful, corrosive chemical used to clear blocked drains and pipes, and to strip stubborn grease, paint and grime from concrete, brick and other hard surfaces. It's highly effective, but it's a serious hazard if handled carelessly — read this guide fully before use.

Before you start — this one matters

- **Corrosive.** Causes severe skin burns and serious eye damage. Wear chemical-resistant gloves and eye/face protection at all times.
- **Always add caustic soda to water — never water to caustic soda.** Adding water to the solid can cause a violent, splashing reaction.
- Always use cold water. Dissolving caustic soda generates heat — the mixture will get hot.
- Use a plastic bucket and stir with a wooden spoon or stick — not metal. Caustic soda reacts with many metals to release flammable hydrogen gas.
- **Do not use on aluminium, zinc, galvanised steel or acrylic surfaces** — it reacts with these and can generate flammable gas.
- Don't mix with any other chemicals.
- Never pour neat, undissolved caustic soda directly into a drain — always dissolve it first.
- Work in a well-ventilated area. Avoid breathing in dust when handling the pearls.
- Full safety information is in the product's Safety Data Sheet — ask us if you need a copy.

How to use it

Always dissolve the pearls in cold water first, adding caustic soda to the water — never the other way round.

• Blocked drains & pipes

- 1 Gradually add **250g caustic soda to 3L cold water** in a plastic bucket, stirring gently with a wooden stick.
- 2 The solution will heat up — let it stand briefly if needed.
- 3 Pour immediately into the drain.
- 4 Leave for 20 minutes.
- 5 Flush with boiling water. Repeat if the blockage persists.

• Concrete, brick & paved surfaces

- 1 Gradually add **125g caustic soda to 5L cold water** in a plastic bucket, stirring gently with a wooden stick.

- 2 Pour onto the stained area and scrub with a brush.
- 3 Leave for around 20 minutes.
- 4 Rinse thoroughly with clean cold water. Repeat if necessary.
- 5 Take care when working near plants or grass — caustic soda will damage them.

Product details

Formats	2.5kg tub / 5kg / 25kg pearl
Composition	Sodium hydroxide (NaOH), high purity pearl
Classification	Corrosive — Skin Corrosion Cat 1, Serious Eye Damage Cat 1

Not suitable for: aluminium, zinc, galvanised steel or acrylic surfaces.