

Random splits overstate transfer
SFRC shear
deep beams
carbonation
FRP shear
46%
48%
56%
27%
28%
13%
21%
20%
19%
5%
3%
4%
random five-fold
leave-one-programme-out
0.2
0.3
0.4
0.5
0.6
0.7
0.8
new-programme RMSE (log units)