

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	06-Jul-23
Jam Berangkat	09.00 WIB
Jam Repair	11.15 S/D 16.15
Jam Kembali	19.40 WIB
Qty Unit Repair	1 pcs
Assy No	21T0645170-01
Type Unit	PC2000-11
Jumlah Man Power	1 Orang
Driver	
Methode Repair	Ganto connector

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
-	-	-

1.Observasi problem terminal lepas yang terjadi pada assy 21T0645170-01 di posisi marker CN-A04 connector 937928400 colour Yellow pada pin connector A6.


2.Proses repair ganti connector 937928400 dikarenakan lock terminal dalam connector patah

3.Setelah repair selesai,connector di pasang ke unitnya dan selanjutnya unit di uji coba di starter dan hasilnya "OK"

1.Terminal push out pada wire colour Yellow



2.Repair ganti connector




3.Connector dipasang ke unitnya



4.Assy No



5.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman