

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	11-Aug-23
Jam Berangkat	12.45 WIB
Jam Repair	14.50 S/D 17.05
Jam Kembali	19.45 WIB
Qty Unit Repair	12 pcs
Assy No	-
Type Unit	PC210 HARVESTER
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness

☐ BEI

☒ NON BEI

Couse of Defect

☐ BEI


☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	1060-16-0122	30 Pcs
Terminal	DT04-2P-E005	15 pcs
Retainer	W2P	15 pcs

1. Modif connector untuk Blower PC210 HARVESTER sebanyak 15 pcs

Before :



After :



2. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman