

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	13-Oct-23
Jam Berangkat	09.45 WIB
Jam Repair	13.05 S/D 16.25 WIB
Jam Kembali	19.10 WIB
Qty Unit Repair	3 pcs
Assy No	-
Type Unit	PC210 HARVESTER
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI

Cause of Defect ☐ BEI ☒ NON BEI





MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	1062-16-0122	36 Pcs
Terminal	1060-16-0122	18 pcs
Connector	DT06-6S-EP06	3 Pcs
Connector	DT04-6P-E005	3 Pcs
Retainer	W6P	3 Pcs
Retainer	W6S-P012	3 Pcs
Tape	WHVTA 19*20B	600 mm


1. Modif wire harness PC210 HARVESTER 3 unit

Before :

After :



2. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman