

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	23-Feb-24
Jam Berangkat	WIB
Jam Repair	13.20 S/D 14.45
Jam Kembali	20.00 WIB
Qty Unit Repair	1 pcs
Assy No	-
Type Unit	PC135F-10M0
Jumlah Man Power	2 Orang
Driver	1 Orang
Methode Repair	Sambung Wire

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Wire	AVS 0,85 B	150mm
Terminal	B1,25	2 Pcs
Terminal	1062-16-0122	1 Pcs
Tape	WHVTA 19*20 B	250 mm
Sumitube	+ES2000-1	80 mm

1.Repair wire putus colour Red dan Black pada unit PC135F-10M0 1 unit

Before :



After :



2.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman