

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	06-May-24
Jam Berangkat	08.25 WIB
Jam Repair	10.45 s/d 15.50
Jam Kembali	19.00 WIB
Qty Unit Repair	22 pcs
Assy No	14X0625321
Type Unit	D 65 E
Jumlah Man Power	3 Orang
Driver	-
Methode Repair	Penambahan circuit dan ganti lampu

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Wire	AVS 0,85 B	2.05 Meter
Wire	AVS 0,85 B-W	2.25 Meter
Wire	AVS 0,85 R-W	2.25 Meter
Wire	AVS 0,85 Y-B	5.47 Meter
Wire	AVS 0,85 Y	0.85 Meter
Terminal	1062-16-0122	12 pcs
Terminal	7116-2873	12 pcs
Terminal	B-2	18 Pcs
Terminal	300502-0	12 Pcs
Terminal	300501-0	6 Pcs
Terminal	110500-2	18 Pcs
Terminal	7114-1471	6 Pcs
Rubber Seal	7157-3570	12 pcs
Rubber Seal	7157-7811-80	6 Pcs
Sleeve	7120-8012	6 Pcs
Sleeve	7120-1010	18 Pcs
Retainer	W2P	6 Pcs
Retainer	7157-6720	6 Pcs
Connector	DT04-2P-CE03	6 Pcs
Connector	7123-6423-30	6 Pcs
Sumitube	SA3-1	0.93 Meter
SH Tube	SH TUBE D5	0.46 Meter
COT	COT D5	9.24 Meter
VO	VO-B 5*6	0.66 Meter
Lampu	Lampu LED putih	16 pcs
Resistor	R 220 ohm 0.5W	16 pcs


1. Modif harness GAUGE dari assy 14X0625321 ke assy 14X-06-J4510 sebanyak 6 pcs

2. Melakukan Repair Lampu Bulb diganti ke LED sebanyak 16 pcs

Before



After



Before



After



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman